

# Oil Field Environmental Incident Summary

**Incident:** 20150119090357      **Date/Time of Notice:** 01/19/2015 09:03

**Responsible Party:** PETRO-HUNT, L.L.C.

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** L.M. THOMPSON 7D-4-4H

**Field Name:** CHARLSON

**Well File #:** 17859

**Date Incident:** 1/18/2015      **Time Incident:** 09:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 95

**Sec:** 8

**Qtr:**

**Location Description:**

**Submitted By:** Derek Enderud

**Received By:**

**Contact Person:** Derek Enderud  
PO BOX 935  
BISMARCK, ND 58502

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	260	Barrels	260	Barrels	260	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/7/2016

**Clean Up Concluded:** 1/18/2015

**Risk Evaluation:**

None.

**Areal Extent:**

Contained inside tank berm.

***Potential Environmental Impacts:***

None.

***Action Taken or Planned:***

Oil was removed with vac truck and put back into tank. Dike was then flushed with 10 bbls freshwater, freshwater was then removed by vac truck and disposed of at Petro-Hunt's south plant disposal system in the Charlson field, SW 7-T153N-R95W.

***Wastes Disposal Location:***

***Agencies Involved:*** Amelia Pennington with Bureau of Land Management was notified at 07:47 am, 1/19/15.

Rick Hutchens with NDIC was notified of incident at 09:52 am, 1/18/15.

***Updates***

---

***Date:*** 1/20/2015    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary, this spill impacted areas on location. NDIC retains oversight.